

## CENTRAL INTELLIGENCE AGENCY

## INFORMATION REPORT

This Document contains information affecting the National Defense of the United States, within the meaning of Title 18, Sections 793 and 794, of the U.S. Code, as amended. Its transmission or revelation of its contents to or receipt by an unauthorized person is prohibited by law. The reproduction of this form is prohibited.

SECRET/CONTROL -- U.S. OFFICIALS ONLY

25X1

COUNTRY	East Germany	REPORT	
SUBJECT	Soviet Tank Repair Shop at Wuensdorf	DATE DISTR.	10 March 1954
DATE OF INFO.		NO. OF PAGES	2
PLACE ACQUIRED		REQUIREMENT NO.	RD
		REFERENCES	25X1

This is UNEVALUATED Information

THE SOURCE EVALUATIONS IN THIS REPORT ARE DEFINITIVE.  
THE APPRAISAL OF CONTENT IS TENTATIVE.  
(FOR KEY SEE REVERSE)

25X1

1. Vehicles:

The following vehicles are attached to the unit:

- a. Truck with hoisting gear
- b. Bus (This vehicle takes people living in Brandenburg from Wuensdorf to the Potsdam railroad station on Saturdays, and picks them up from the station on Sundays.)

25X1

2. Repairing of Armored Vehicles:

- a. At the present time the only tracked vehicles are T-34's with 85 millimeter and 76 millimeter guns. Wheeled vehicles under repair include mobile work-shops, motorcycles with sidecars, jeeps and scout cars. other types of vehicles will come in for repair when the T-34 program is completed and employees are sufficiently experienced.
- b. Up to now only engine repairs have been observed. Only in rare instances are new engines mounted in place of the old ones.
- c. Engine parts and engine supplies are kept in two sheds.
- d. The number of armored vehicles arriving varies every half month. More come at the beginning of the month than in the middle of the month. Armored vehicles arrive along the branch railway line at a ramp, are unloaded and put into a parking place. The vehicles After inspection, they are repainted and proceed to the trial grounds north of the parking place. After they have been washed in a washing shed, they are once more inspected, and finally transported away.

25X1

25X1

25 YEAR RE-REVIEW

SECRET/CONTROL - U.S. OFFICIALS ONLY

STATE	ARMY	EV	X	NAVY	X	AIR	X	FBI		AEC					
-------	------	----	---	------	---	-----	---	-----	--	-----	--	--	--	--	--

(Note: Washington Distribution Indicated By "X"; Field Distribution By "#".)

SECRET/CONTROL - U.S. OFFICIALS ONLY

- 2 -

25X1

e. The Wuensdorf installation is the central workshop; minor repairs are carried out by the individual units. Therefore all vehicles at Wuensdorf are there for general overhaul.

f. The following number of vehicles were repaired at Wuensdorf:

In August: 20 T 34/85's and T 34/76's  
In September: 22 T 34/85's and T 34/76's  
In October: 23 T 34/85's and T 34/76's

3. Fuel Tank:

A fuel tank with eight millimeter walls and a capacity of approximately 300 liters was tested at 15 atmospheres.

4. Personnel:

Soviet personnel are being gradually withdrawn and more skilled German workers for all sections are coming from the aircraft engine works at Ludwigsfelde.

SECRET/CONTROL - U.S. OFFICIALS ONLY